



Solving environment-related business problems worldwide

www.deltaenv.com

27141 Aliso Creek Road • Suite 270
Aliso Viejo, California 92656 USA

949.362.3077 800.477.7411
Fax 949.362.0290

April 14, 2005

Mr. Sam Stevens
Los Angeles County Department of
Public Works
900 South Fremont Avenue
Alhambra, California 91803

Sent by UPS

Subject: Quarterly Update Report Submittal

Dear Mr. Stevens:

On behalf of Atlantic Richfield Company, Delta Environmental Consultants, Inc. is submitting the enclosed Quarterly Site Status Report for the First Quarter 2005. The enclosed quarterly report was prepared for the following ARCO Facility:

ARCO Facility No.

1592

LADPW Site No.

EP-1 011979-037116

Location

5 West Foothill Blvd, Arcadia

If you have any questions, please contact the undersigned at (949) 360-5789.

Sincerely,

DELTA ENVIRONMENTAL CONSULTANTS, INC.

A handwritten signature in cursive script, appearing to read "Amy R. Mora".

Amy R. Mora
Project Manager

Enclosure: Atlantic Richfield Company Quarterly Site Status Report

cc: Mr. Gordon Terhune, Atlantic Richfield Company, La Palma, California
Mr. John Nahas, 5 West Foothill Boulevard, Arcadia, California

**ATLANTIC RICHFIELD COMPANY QUARTERLY SITE STATUS REPORT
FIRST QUARTER 2005
APRIL 15, 2005**

ARCO Facility No.: 1592 Address: 5 West Foothill Boulevard, Arcadia, California
Atlantic Richfield Co. Env. Manager / Phone No.: Gordon Terhune / (562) 438-3871
Consulting Co. / Contact Person / Phone No.: Delta Environmental / Amy Mora / (949) 360-5789
Primary Agency / Contact Person / Regulatory ID No.: County of Los Angeles Department of Public works (LADPW) /
Sam Stevens / EP-1 011979-037116

WORK PERFORMED THIS QUARTER (First - 2005):

1. Submitted the fourth quarter 2004 *Quarterly Site Status Report* to the LADPW.

WORK PROPOSED FOR THE NEXT QUARTER (Second - 2005):

1. Submit Quarterly Site Status Report.

Current Phase of Project:	<u>Assessment/Closure</u>		
Depth to Groundwater:	<u>200+ feet</u>	Measured <u> </u>	Estimated <u>X</u>
Groundwater Gradient:	<u>Unknown</u>	(Magnitude)	<u>Unknown</u> (Direction)


ATTACHMENTS: Site Location Map (Figure 1)
Site Map (Figure 2)

DISCUSSION:

The hydrocarbon-impacted soil at the site has been sufficiently assessed vertically and horizontally. Therefore, on behalf of Atlantic Richfield Company, Delta requests that no further actions be required of Atlantic Richfield Company for this site.


If you have any questions or comments concerning this correspondence, please contact Amy Mora at (949) 360-5789.

DELTA ENVIRONMENTAL CONSULTANTS, INC.



Amy Mora
Project Manager

4/14/05
Date



GENERAL NOTES:
 BASE MAP FROM 3-D TOPO QUADS
 MT. WILSON, CA. QUADRANGLE
 7.5 MINUTE TOPOGRAPHIC MAP
 1966
 PHOTOREVISED 1988





FIGURE 1


SITE LOCATION MAP
 ARCO FACILITY NO. 1592
 5 W. FOOTHILL BOULEVARD
 ARCADIA, CA.

PROJECT NO. AM03-169		DRAWN BY	
FILE NO. A3-808-03		PREPARED BY A. BAIRD	
DATE 09 DEC 03	REV. 0	REVIEWED BY	





LEGEND

- B-1 ● SOIL VAPOR EXTRACTION WELL LOCATION
- B-2 ● SOIL BORING LOCATION
- T5A ▼ TANK SOIL SAMPLE LOCATION
- D4A ▼ DISPENSER SOIL SAMPLE LOCATION
-  APPROXIMATE LIMIT OF OVEREXCAVATION




FIGURE 2

SITE MAP
ARCO FACILITY NO. 1592
5 WEST FOOTHILL BOULEVARD
ARCADIA, CA.

PROJECT NO.
AM03-169

DRAWN BY
K. MARTIN

FILE NO.
A3-169-01

PREPARED BY
A. BAIRD

DATE
17 MAR 04

REV. 0
REVIEWED BY

